


Examples of Unacceptable Stack Designs



The examples on this page do not meet the requirements of Permit By Rule 106.436. The cap on Stack A obstructs vertical discharge of air contaminants. Stack B, a goose neck, also prevents vertical discharge. Stack C, which comes out of the building horizontally, simply does not provide for vertical discharge